

AllWest Project Experience 2013 - 2024

Retail

NAME / LOCATION

CLIENT / ASSIGNMENT

PROPERTY DATA

Second Street Crossing Shopping Center Davis, CA Winn Communities Sacramento, CA

ALTA, Environmental & Property Condition Assessments



46,330 sf, 4 building shopping center

AllWest's ESA provided confidence to buyer that adjoining Superfund site was not a material concern

Tulare Village Tulare, CA Stearns & Ryan Torrance, CA

Property Condition Assessment



160,000 sf, 5 building service retail built in 1970

AllWest PCA was provided to potential buyers as a baseline evaluation

Downtown Retail San Carlos, CA **Black Mountain Properties**

ALTA, Environmental, Property Condition and Seismic Assessments



3 buildings primarily restaurant use 25,000 sf

AllWest conducted myriad of studies designed for acquisition purposes

Hamilton Marketplace Novato, CA Grosvenor Americas San Francisco, CA

Environmental and Property Condition Assessments



4 buildings 91,000 sf Retail Center on 8.8 acres

AllWest reports aided \$67 million disposition



AllWest Project Experience 2013 - 2024

Retail

NAME / LOCATION

CLIENT / ASSIGNMENT

PROPERTY DATA

Washington Square Petaluma, CA Confidential

Phase I, Soil, Soil Vapor and Groundwater Assessments



8 buildings 230,000 sf Retail Center

Assisted client define hazmat release, addressing issues with regional agency

Borel Square Shopping Center San Mateo, CA CBRE San Jose, CA

Property

Condition Assessment



4 buildings 92,813 sf Built 1968 & 2000

Report aided property acquisition

SF Jewelry Center San Francisco, CA Swift Real Estate San Francisco, CA

Phase II



Confirmed site environmental conditions

Four grocery anchored neighborhood retail

Seattle, WA Metro Area

centers

Donahue Schriber Realty Group Costa Mesa, CA

Property

Condition & Seismic Assessments



26 buildings, 350,660 sf

AllWest completed eight assessments in a 10 day span concluding on December 22

Neighborhood Retail Fountain Valley, CA **Family Trust**

Phase I, II and IIa Assessments to determine costs associated with

site dry cleaners



3 buildings on 2 acres

Reports aided Trust financial dissolution



AllWest Project Experience 2013 - 2024

Retail

NAME / LOCATION

CLIENT / ASSIGNMENT

PROPERTY DATA

The Tiffany Building 360 Post St. San Francisco, CA

Ponte Gadea, USA

Environmental, Property Condition & Seismic Peer Reviews coupled with site visits to confirm findings and supplement



11 story, 96,884 sf retail and office building

Reports aided fast paced acquisition

Del Monte Center Monterey, CA Balboa Retail Investors Santa Monica, CA

Property Condition and Seismic Assessments



2 story, 80,723 sf retail building, originally occupied by Mervyns

Reports aided property disposition

Edgewater on Monterey Bay Sand City, CA Windsor Medical Park, L.P. Mill Valley, CA

Environmental and Property Condition Assessments and ALTA Survey



One building, three tenant retail structure 25,201 sf

Due diligence reports aided property acquisition

Redmond Town Center Redmond, WA DRA Realty Advisors New York, NY

Environmental Site Assessments



19 retail/office buildings 67.7 acres 506,433 sf



AllWest Project Experience 2013 - 2024

Retail

NAME / LOCATION

CLIENT / ASSIGNMENT

PROPERTY DATA

National Dollar Store San Francisco, CA Harrigan Weidenmuller San Francisco. CA

Hoist Removal



Operating retail store

Hoist removal completed while store remained open

500 Broadway Santa Monica, CA KRE Capital Beverly Hills, CA

Property Condition Assessment Environmental Assessment Seismic Assessment



Retail building single story 37,500 sf

Potential redevelopment site

Former Washington Mutual Bank Branches Coastal, CA MetLife Los Angeles, CA

ALTA Surveys



14 bank branches Santa Rosa to San Diego